



LK46

Instructions








13mm



3,6,9
mm




4mm




LW004

x 1




LW020

x 1



LR034

x 1




LR071

x 1



PS054

x 1



PS624

x 1




PS055

x 1




PS437

x 1




MS1016

x 2




LR005

x 1




LR006

x 1




LR064

x 1



LR065

x 1




LR066

x 2




FS061
(M8x35)

x 6




FS067
(M8x20)

x 16




FW021
(M8)

x 38




FN080
(M8)

x 12



FN060
(M8)

x 4



PS414
(M8)

x 20



PS065
(M8)

x 6



PS419

x 12




FS105
(M8x55)

x 2



FS109
(M8x90)

x 2



PS204

x 2



PS203

x 4



LA074

x 2



FW085
(M6)

x 4








FS170
(M6x16)


x 4




LK46FI_b




6.




7.



8.




9.




**LR071
x1**






10.




11.




**1st - 3mm
2nd - 6mm
3rd - 9mm**




17.




18.




19.









20.




21.







28.




29.




30.



31.



32.



33.

